


# 22. WIRE DIAGRAM

## XCITING 500



B BLACK	BR BROWN
G GREEN	GR GRAY
O ORANGE	SB SKY BLUE
L BLUE	LG LIGHT GREEN
W WHITE	V VIOLET
Y YELLOW	R RED

HAZARD SW	
WR HA	
OFF	
COLOR	BL Y/B

PASSING SW	
BAT4 HI	
FREE	
PUSH	
COLOR	BR/L L

STARTER SW	
E ST	
FREE	
PUSH	
COLOR	G Y/R

ENGINE STOP SW	
IG BAT3	
OFF	
RUN	
COLOR	B/W B/G

HORN SW	
BAT4 HO	
FREE	
PUSH	
COLOR	BR/L LG

WINKER SW			
WR	R	L	
N			
L			
COLOR	GR	SB	O

DIMMER SW			
LD	HL	HI	LO
(N)			
HI			
COLOR	W/L	L	W

COMB SW			
BAT2	IG	E	BAT1 HA
LOCK			
OFF			
ON			
COLOR	B	B/W	G R B/L

LIGHTING SW			
BAT4	PO	TL	HL
(N)			
P			
(N)			
H			
COLOR	BR/L	BR/W	BR W/L